

NEWS

i-Checker Full/Semi-Automatic Inspection System




Inspect your analog indicator semi-automatically!

- The pointer of the analog indicator is positioned just before the measuring point automatically via Mitutoyo's Semi-automatic Measurement function. After that, inspection begins simply by adjusting the pointer position with the jog-dial. Because of this function, measurement time is reduced and user fatigue is eliminated. Additionally all functions necessary for inspection are combined in the control box for easy operation.




Attached bore gage accessory set (optional)



Attached test indicator accessory set (optional)

Fully automatic inspection of digital indicator

- The Automatic Measurement function, in tandem with a digital indicator makes the spindle move so that measurement data is acquired automatically. Therefore, manual adjustment to the measurement position is unnecessary and the efficiency of every inspection is enhanced.



Create and printout a simplified inspection certificate

- It is possible to create, edit and print out your own inspection certificate, and that data can be saved as a CSV file.

Inspection Certificate			
Issue No.	MR002	Name of Inspection Standard	ISO R463(1985)
Date of Issue	5/29/2001	Unit	mm
Product Name	Dial Gauge	Scale Interval	0.01 mm
Manufacturer	Mitutoyo	Measuring Range	10 mm
Code No.	2549P	Reference Point	0 mm
Serial No.	100101	End Point	10 mm
Date of Inspection	5/29/2001		
Temperature	20°C		
Inspector	Mitutoyo Japan		
Inspection Item Name	Result	Permissible Value	Judgment
Any One-Tenth Revolution	2.52 μm	5 μm	GO
Any Half Revolution	3.14 μm	10 μm	GO
Any Two Revolutions	5.1 μm	15 μm	GO
The Total Measuring Range	6.1 μm	20 μm	GO
Repeatability	+0.14 μm	±5 μm	GO
Max. Measuring Force	0.8 N	1.5 N	GO
Difference in Measuring Force	0.2 N	0.6 N	GO
Inspection Item Name	Judgment		
Inspection of Function and Appearance	GO		

Inspection Certificate			
Issue No.	MR002	Name of Inspection Standard	ISO R463(1985)
Date of Issue	5/29/2001	Unit	mm
Product Name	Dial Gauge	Scale Interval	0.01 mm
Manufacturer	Mitutoyo	Measuring Range	10 mm
Code No.	2549P	Reference Point	0 mm
Serial No.	100101	End Point	10 mm
Date of Inspection	5/29/2001		
Temperature	20°C		
Inspector	Mitutoyo Japan		
Inspection Item Name	Result	Permissible Value	Judgment
Any One-Tenth Revolution	2.52 μm	5 μm	GO
Any Half Revolution	3.14 μm	10 μm	GO
Any Two Revolutions	5.1 μm	15 μm	GO
The Total Measuring Range	6.1 μm	20 μm	GO
Repeatability	+0.14 μm	±5 μm	GO
Max. Measuring Force	0.8 N	1.5 N	GO
Difference in Measuring Force	0.2 N	0.6 N	GO
Inspection Item Name	Judgment		
Inspection of Function and Appearance	GO		

Graphs showing measurement results over time.

Signature: _____

SPECIFICATIONS

i-Checker main unit

Order No. 170-303A	
Item	Contents
Measuring Range	100mm/4"
Resolution	0.02μm/1.24μin
Accuracy	vertical position $\pm(0.2+L/100)\mu\text{m}$ L = Arbitrary length
(at 20°C)	lateral position $\pm(0.3+2L/100)\mu\text{m}$ L = Arbitrary length
Feed speed	4mm/sec (max.)
Drive method	Motor drive
Measuring Unit	Reflective-type metal linear encoder
Thermal expansion coefficient of measurement mode	$(8\pm 1)\times 10^{-6}/\text{K}$
Measurement method	Semiautomatic measurement Fully automatic measurement* ¹ Digimatic Indicator with RS-232C output* ²
Input data connector	Digimatic data input connector X1* ³ Flat cable connector 10pin/equivalent to XG4-1301 from OMRON* ⁴
Dimensions (W x D x H)	184 x 225 x 532mm/7.24" x 8.86" x 20.94"
Operating temperature range	20°C $\pm 3^\circ\text{C}$
Operating humidity range	58%RH \pm 15%RH (Only free of condensation)
Storage temperature range	-10°C to 50°C
Storage humidity range	5%RH to 90%RH (Only free of condensation)
Power supply	100VAC to 240VAC $\pm 10\%$, 50/60Hz
Mass	20kg/441lbs

*¹ Automatic measurement requires the indicator's connection cable. Additionally some form of indicator, along with a connecting machine (the optional accessory for indicator as a digimatic power-supply unit on EF counter) will be needed.

*² The indicator that can be measured via RS-232C is the one equipped with the function to receive the "send data" request command form from the main unit and can output the counter value to the main unit.

*³ For the RS-232C connector, uses the connector from a computer

*⁴ The connection cable connector is equivalent to MIL-DTL-83503/7D-10.



*Personal computer and printer are optional.

i-Pak


Item	Contents										
Supporting industrial standard* ¹	ISO, JIS, JMAS, DIN, VDI/VDE/DGQ, ANSI/ASME										
Basic functions	<ul style="list-style-type: none"> •Create an inspection standard conforming to the industrial standards. •Create an original inspection standard, though customization industrial standard •Inspect an indicator using a newly created inspection standard (inspection for accuracy, dispersion) •Create and print of simplified inspection certificates. •Display measurement results graphically. 										
Other functions	<table border="1"> <tr> <td>Warning</td><td>This window is displayed when the measured value exceeds the limit during the semiautomatic inspection</td></tr> <tr> <td>Re-measurement</td><td>It is possible to confirm the measuring data, by re-measuring the specified position after the inspection</td></tr> <tr> <td>Display of inspection manual</td><td>Display the inspection manual when starting an inspection*²</td></tr> <tr> <td>Retry</td><td>Use for retry the "measurement positioning". (it removes the hysteresis of indicator automatically)</td></tr> <tr> <td>Password</td><td>Restricted access through by password registration</td></tr> </table>	Warning	This window is displayed when the measured value exceeds the limit during the semiautomatic inspection	Re-measurement	It is possible to confirm the measuring data, by re-measuring the specified position after the inspection	Display of inspection manual	Display the inspection manual when starting an inspection* ²	Retry	Use for retry the "measurement positioning". (it removes the hysteresis of indicator automatically)	Password	Restricted access through by password registration
Warning	This window is displayed when the measured value exceeds the limit during the semiautomatic inspection										
Re-measurement	It is possible to confirm the measuring data, by re-measuring the specified position after the inspection										
Display of inspection manual	Display the inspection manual when starting an inspection* ²										
Retry	Use for retry the "measurement positioning". (it removes the hysteresis of indicator automatically)										
Password	Restricted access through by password registration										

*¹ Refer to the reference materials (attached paper) for details about support for industrial standards.

*² To create an inspection manual, it is necessary to install the application software used to create the document, in the computer where i-Pak is installed.

Operation Box

Item	Contents
Switch	Jog-dial
	Shuttle moves main unit spindle up and down.
	[DATA] button
	Use for acquiring the measurement data.
	[RETRY] button
	Handy for retrying "measurement positioning". Automatically removing indicator hysteresis
	[CANCEL] button
	Deletes previous data and measures it again.
	[STOP] switch
	Forcibly halts operation.
Dimension (W x D x H)	170 x 100 x 55mm/6.69" x 3.94" x 2.17"
Mass	1kg/2.2lbs.



Applicable computer and printer*¹

Item	Operating environment (minimal condition)	Suggested environment
Machine type	IBM-PC compatible	
OS	Windows 2000 or NT4.0 (SP3 or newer + IE 5.0 or newer)	
Microprocessor	Pentium III 450MHz	Pentium III 600MHz or more
Memory	64MB	128MB or more
HDD	more than 50MB free space except for OS	more than 1GB free space except for OS
Drive	CD-ROM, FDD	
Interface	Parallel (for printer) X1 RS-232C (for full-automatic measurement) X1	
Slot	PCI (PCI2.1 Compatible) X1: for control board	
Screen resolution	1024 (W) x 768 (H) x High Color (16Bit)	1024 (W) x 768 (H) x True Color (32Bit)


*¹ Windows supporting printer

NEW Product News



DIMENSIONS

Unit: mm (inch)



Optional accessories

Attachment

02ASK000	Test indicator accessories set (ø6 stem)
02ASK180	Test indicator accessories set (ø8 stem)
02ASK370	Test indicator holder (ø6 stem)
02ASK380	Test indicator holder (ø8 stem)
02ASK110	Bore gage accessories (1 set)
902803	ø6 dovetail grooved stem
902804	ø8 dovetail grooved stem

Stem bush

02ASK040	Stem bush ø6
02ASJ856	Stem bush ø8
02ASK150	Stem bush ø8, short
02ASK050	Bush ø9.5*
02ASK060	Stem bush ø12
02ASK070	Stem bush ø15
02ASK080	Stem bush ø20
02ASK090	Stem bush 3/8"
02ASK130	Case

*Requires 02ASK070

Cable*1

905338	Connecting cable (1m/40")
905409	Connecting cable (2m/80")
936937	Connecting cable (1m/40")
905014	Connecting cable (2m/80")
905387	Connecting cable (1m/40")
905013	Connecting cable (2m/80")

*1: for automatic measurement

Others

02ASK730	Reflector
937179T	Foot switch

Computer Systems

Code No.	Description
64AAA355	Dell System w/17" Monitor included; printer HP-950C deskjet
64AAA356	Dell System w/15" Flat Monitor included; printer HP-950C deskjet

Distributed By:

Willrich Precision
Ph 866-945-5742
email: sales@willrich.com

Mitutoyo
 www.mitutoyo.com

Mitutoyo America Corporation